

DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
Bureau of Maintenance
2nd Street, Port Area, Manila

SITUATIONAL REPORT ON MAJOR ROADS AND BRIDGES DUE TO "6.7-MAGNITUDE EARTHQUAKE"
Status as of 6:00PM, February 11, 2017

AFFECTED AREAS MAJOR/SECONDARY ROAD/BRIDGE Province/City/Municipality (Barangay, Sta. Limits)	DATE REPORTED TO CENTRAL OFFICE	SITUATION	DESCRIPTION OF DAMAGE	ACTION TAKEN (Equipment used/deployed)	PREL. EST. OF DAMAGE (Php)	a. POINTMAN b. CONTACT NUMBER	REMARKS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
REGION XIII							
<u>Surigao del Norte I DEO</u>							
1. Daang Maharlika Road a. (Surigao-Agusan Section and Surigao-Ipil-Lipata Section)	11-Feb-17	Passable to all types of vehicles	Intermittent damaged road section (cracks/buckling/blow-up of concrete/asphalt pavement)	Warning signs and barricades installed on affected areas. Augmentation of equipment and work force are on site. Removal of debris/clearing operation on-going.		a. Edilberto Pejan b. 0998-974-56-51	Passable as per phone call dated February 11, 2017, 11:30AM
2. Malico Bridge K1122+067, Daang Maharlika Road (Lipata-Surigao Section)	11-Feb-17	One lane passable to light vehicles only	Depressed approach slab/damaged concrete railings	Steel Plate and Warning Signs at bridge approaches provided. Heavy Vehicles are diverted to Surigao Wharf Road connecting Surigao City-San Juan Coastal going in and from Lipata Port and Surigao-Agusan Road		a. Edilberto Pejan b. 0998-974-56-51	One Lane Passable to Light Vehicles Only as per email received dated February 11, 2017, 11:18AM
3. Kinabutan I Bridge K1121+642, Daang Maharlika Road (Lipata-Surigao Section)	11-Feb-17	One lane passable to light vehicles only	Cracks/buckling/pop-up of Steel Plate and damaged concrete railing	Steel Plate and Warning Signs at bridge approaches provided. Heavy Vehicles are diverted to Surigao Wharf Road connecting Surigao City-San Juan Coastal going in and from Lipata Port and Surigao-Agusan Road			One Lane Passable to Light Vehicles Only as per email received dated February 11, 2017, 3:02 PM

AFFECTED AREAS MAJOR/SECONDARY ROAD/BRIDGE Province/City/Municipality (Barangay, Sta. Limits)	DATE REPORTED TO CENTRAL OFFICE	SITUATION	DESCRIPTION OF DAMAGE	ACTION TAKEN (Equipment used/deployed)	PREL. EST. OF DAMAGE (Php)	a. POINTMAN b. CONTACT NUMBER	REMARKS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
4. Kinabutan II Bridge K1121+807, Daang Maharlika Road (Lipata-Surigao Section)	11-Feb-17	Passable to light vehicles only	Depressed approach slab/damaged concrete railings	Steel Plate and Warning Signs at bridge approaches provided. Heavy Vehicles are diverted to Surigao Wharf Road connecting Surigao City-San Juan Coastal going in and from Lipata Port and Surigao-Agusan Road			Passable to Light Vehicles Only as per email received dated February 11, 2017, 3:02 PM
5. Friendship Bridge K1118+193, Surigao-San Juan Coastal Road	11-Feb-17	One lane passable to all types of vehicles	Settlement of approach A due to damaged slope protection. Noted cracks on girder.	Warning signs and filling materials provided at bridge approach.			One Lane Passable to all types of Vehicles as per email received dated February 11, 2017, 3:02 PM
6. Banahaw Bidge K1115+425, Surigao-San Juan Coastal Road	11-Feb-17	Passable to all types of vehicles	Damaged slope protection	Warning signs provided at bridge approach.			Passable to all types of Vehicles as per email received dated February 11, 2017, 3:02 PM
7. Other National Roads Surigao-Davao Coastal Road, Magpayang-Mainit Wharf Road, Surigao-San Juan Coastal Road, Surigao Wharf Road	11-Feb-17	Passable to all types of vehicles	Minor Cracks	Warning signs and barricades installed on affected areas.			Passable to all types of Vehicles as per email received dated February 11, 2017, 3:02 PM

Prepared by:

JUMAR G. TABLANDO
Engineer II

Submitted by:

DOMINADOR P. AQUINO
Engineer V
Safety and Disaster Management Coordination Division
Tel. No. 304-3758

Approved by:

ERNESTO S. GREGORIO, JR.
Director IV